

## PRODUCTS

### Connection/ Wiring Diagrams

#### Part Winding Start (Wye Only)

Speed: Single

Phase: 3


Typical Voltage: Dual 230/460

Winding: Y only

Special Feature:

Part winding, start low voltage, 9 leads

**Note:** Normally this is a standard Star-Y dual voltage motor used for part winding start at 230V.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved