


## Connection/ Wiring Diagrams

### Constant Torque (One Winding)

Speed: Two  
Phase: 3  
Voltage: Single voltage only  
Winding: Single winding  
Special Feature: Constant torque

**Note:** Normally provided on two speed units with speed ratio of 2 to 1.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved