

## Connection/ Wiring Diagrams

### One Wye (Two Winding)

Speed: Two


Phase: 3

Voltage: Single voltage only


Winding: Y - Y

Special Feature: Constant torque, variable torque or constant HP


**Note:** Two Windings provided on two speed unit not having speed ratio of 2 to 1.



Low Speed



High Speed



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved