



Connection/ Wiring Diagrams

WYE Only

Speed: Single
Phase: 3
Voltage: Single Voltage Only
Winding: Y only
Special Feature:
Neutral Brought out -
4 leads (3 phase 4 wire)

Note: Phase voltage (lead to neutral) = line volts / Square Root of 3; provided only upon request.



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved