


Connection/ Wiring Diagrams

Star Y

Speed: Single
Phase: 3
Typical Voltage: Dual 230/460
Winding: Star Y


Note: Commonly supplied on smaller HP units from approximately 326T frames and smaller.

Winding




Connection

Low Volts



High Volts



[Home](#) [Email](#)

Copyright © 2000 U.S. Electrical Motors, All rights reserved